



Installing Screw Sets on Handle Holes for Optimal Installation

Applies to: LB-6D-G3 and LB-16D-G3

After using the handles for moving the battery, and before securing the battery to the wall, install the provided screw sets to seal the handle holes.



6D Handle Holes



16D Handle Holes

Tools and Materials

For LB-6D-G3

Provided Materials				Self-Prepared Tool
				
Screw M8*18*2	Screw M8*16*2	Flat Washer*4	Rubber Washer*4	Electric Screwdriver


For LB-16D-G3

Provided Materials				Self-Prepared Tool
				
Screw M8*18*2	Screw M8*16*4	Flat Washer*6	Rubber Washer*6	Electric Screwdriver

Installation Steps


NOTE

- All battery installations (floor standing, wall mounting, and wheel mounting) must follow the steps below.
- When marking drilling positions on the wall using the positioning board, it is recommended to move the two top hole positions (marked by "L" and "R") outward by 4 mm on each side. This step is required to ensure proper screw alignment in Step 2. Skipping it will cause the screw holes to be misaligned.



Step 1: Remove the handles when you don't need them to move the battery.

- Intall the hex key on a handle.
- Press the hex key downward and unscrew the handle.
- Repeat steps a-b to remove all the installed handles.



Step 2: Install all screw sets on all handle holes.

